

ACTi IP Utility Release Notes

Product: IP Utility
Version: v3.5.25 (build 100401)
Release Date: April. 29, 2010

Latest update:

Enhancement

- 1 Add the "Authentication Failed" in the camera profile field to indicate the account name and password are incorrect to get the camera profile ID.
- 2 Add the "Camera Profile Refresh" tab to read the camera profile ID for selected camera. No device search action is taken when Camera Profile Refresh is performed.
- 3 Show the model description if it is available in the device discovery reply message from the device. If it is not available, the internal database is used.
- 4 Update the Product Map database for new camera models
- 5 Compatible to new platformA firmware 3.12 and platformT firmware 4.07

Modification

- 1 Close symbol 「+」 to backup/restore configuration of router. Open symbol 「+」 to backup/restore configuration of server(channel).
- 2 Check firmware version, profile ID (EPL, Platform T) / NTSC/PAL(Platform W) to restore camera or video server(channel)
- 3 Check router version, profile ID (EPL, Platform T) / NTSC/PAL(Platform W) to restore router
- 4 Change the wording of "Clean Status" to "Clean Check Box"
- 5 Only root account could perform configuration restore and firmware/camera profile upgrade.

Limitation

1. Profile pack upgrade only supported by:
 - A. Platform T: FW version v4.06.09 or above
 - B. Platform A IP camera: FW version v3.09.14 or above
 - C. Platform A video server: FW version v3.11.11 or above
- 2 Only Platform T and Platform A support camera profile pack upgrade
3. Please do not power off or reboot your device when upgrading firmware

4. Only device discovery supports in the decoder and CAM-xxxx camera. The rest functions of IP Utility should not be used.